



Rely on Ross. We do it right!

“D” Waste Codes

D001	D012	D023	D034
D002	D013	D024	D035
D003	D014	D025	D036
D004	D015	D026	D037
D005	D016	D027	D038
D006	D017	D028	D039
D007	D018	D029	D040
D008	D019	D030	D041
D009++	D020	D031	D042
D010	D021	D032	D043
D011	D022	D033	

“F” Waste Codes

F001	F011
F002	F012
F003	F019
F004	F024
F005	F025
F006	F032
F007	F034
F008	F035
F009	F037
F010	F038
	F039+

“K” Waste Codes

K001	K025	K050	K102	K141
K002	K026	K051	K103	K142
K003	K027	K052	K104	K143
K004	K028	K060	K105	K144
K005	K029	K061	K106	K145
K006	K030	K062	K107	K147
K007	K031	K069	K108	K148
K008	K032	K071	K109	K149
K009	K033	K073	K110	K150
K010	K034	K083	K111	K151
K011	K035	K084	K112	K156
K013	K036	K085	K113	K157
K014	K037	K086	K114	K158
K015	K038	K087	K115	K159
K016	K039	K088	K116	K161
K017	K040	K093	K117	K169
K018	K041	K094	K118	K170
K019	K042	K095	K123	K171
K020	K043	K096	K124	K172
K021	K044	K097	K125	K174+
K022	K045	K098	K126	K175+
K023	K046	K099	K131	K176+
K024	K047	K100	K132	K177+
	K048	K101	K136	K178
				K181

“P” Waste Codes

P001	P020	P041	P063	P082	P105	P127
P002	P021	P042	P064	P084	P106	P128
P003	P022	P043	P065	P085	P108	P185
P004	P023	P044	P066	P087	P109	P188
P005	P024	P045	P067	P088	P110	P189
P006	P026	P046	P068	P089	P111	P190
P007	P027	P047	P069	P092+	P112	P191
P008	P028	P048	P070	P093	P113	P192
P009	P029	P049	P071	P094	P114	P194
P010	P030	P050	P072	P096	P115	P196
P011	P031	P051	P073	P097	P116	P197
P012	P033	P054	P074	P098	P118	P198
P013	P034	P056	P075	P099	P119	P199
P014	P036	P057	P076	P101	P120	P201
P015	P037	P058	P077	P102	P121	P202+
P016	P038	P059	P078	P103	P122	P203
P017	P039	P060	P081	P104	P123	P204
P018	P040	P062				P205

“U” Waste Codes

U001	U020	U038	U058	U077	U095	U115	U134+	U155	U176	U196	U217	U243	U373
U002	U021	U039	U059	U078	U096	U116	U135	U157	U177	U197	U218	U244	U387
U003	U022	U041	U060	U079	U097	U117	U136	U158	U178	U200	U219	U246	U389
U004	U023	U042	U061	U080	U098	U118	U137	U159	U179	U201	U220	U247	U394
U005	U024	U043	U062	U081	U099	U119	U138	U160	U180	U202*	U221	U248	U395
U006	U025	U044	U063	U082	U101	U120	U140	U161	U181	U203	U222	U249	U404
U007	U026	U045	U064	U083	U102	U121	U141	U162	U182	U204	U223	U271	U409
U008	U027	U046	U066	U084	U103	U122	U143	U163	U183	U205	U225	U278	U410
U009	U028	U047	U067	U085	U105	U123	U144	U164	U184	U206	U226	U279	U411
U010	U029	U048	U068	U086	U106	U124	U145	U165	U185	U207	U227	U280	
U011	U030	U049	U069	U087	U107	U125	U146	U166	U186	U208	U228	U328	
U012	U031	U050	U070	U088	U108	U126	U147	U167	U187	U209	U234	U353	
U014	U032	U051	U071	U089	U109	U127	U148	U168	U188	U210	U235	U359	
U015	U033	U052	U072	U090	U110	U128	U149	U169	U189	U211	U236	U364	
U016	U034	U053	U073	U091	U111	U129	U150	U170	U190	U213	U237	U367	
U017	U035	U055	U074	U092	U112	U130	U151+	U171	U191	U214+	U238	U372	
U018	U036	U056	U075	U093	U113	U131	U152	U172	U192	U215+	U239		
U019	U037	U057	U076	U094	U114	U132	U153	U173	U193	U216+	U240		
						U133	U154	U174	U194				

EPA hazardous waste codes that are acceptable for incineration based on the Ohio Permit and the Federal Permit for Ross Incineration Services, Inc. Ross Incineration reserves the right to suspend receipts of any given code. Please contact the Customer Service Department at 1-800-878-7677 for verification.

+ Contact customer service for availability for these waste codes.

++ Contact customer service for availability if mercury concentration is greater than 260 ppm.

* U202 is no longer regulated by U.S. or Ohio EPA.